Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Mine Name: **Jimmie Boone**Mine ID: **91**

Navajo AUM Western Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

20074.063.017.0020

August 2011

Part I	Site Identification, Location and Status			
Site Names ar	nd ID numbers	s as applicable		
Mine ID:	91			
Map ID:	W1			
CERCLIS:	NNN0009092	04		
Navajo Aban	doned Mine La	and Reclamati	ion Program: NA-0	101
Local name /	Aliases: Jimm	ie Boone A &	B; Jimmie Boone A; J	immie Boone B; Jimmy Boone
Chapter and	local area: Bo	daway / Gap		
County: Coc	onino	State: Arizon	a	
Lat/Long:	36.804318352	5 N / -111.600	881692 W	
Nearby road	and highway:	US-89	Local Post Office:	Tuba City, AZ
Surface Land Status: check one or more and provide ownership and contact information below				
Tribal Trust I Private Bureau of La State			Public lands Tribal Fee Land Allotment Fee land	
Subsurface M	lineral Rights:			
No informatio	n on subsurface	e mineral rights	s ownership was found	in the EPA/AUM Database.
Claim and op	erator inform	ation:		

The mine surface land status is classified as Tribal Trust Land. Historical documents identified the operator of the mine as D.L., T.L., & F.E. Lee in 1954. No additional historical ownership / lease information was identified in the EPA / AUM database.

Number of residential structures within 200 feet of mine: None

Part II Summary of Radiological Readings

Mine ID: 91

Highest gamma radiation measurement: 94,571 counts per minute (cpm)


Background Average: 12,338 cpm **Two Times Background:** 24,676 cpm

Describe any other radiological measurements:

A total of 2,972 gamma radiation measurements were collected from the mine site, ranging from 7,957 cpm to 94,571 cpm. Measurements collected in the vicinity of the waste rock were found at a maximum level of approximately 95,000 cpm. The measurements are represented in Figures 1 and 2.

Distribution Chart and Statistics:

Site Gamma Radiation Statistics				
Number of Readings	2,972			
Minimum (cpm)	7,957			
Maximum (cpm)	94,571			
Mean (cpm)	19,977			
Median (cpm)	17,536			
Standard Deviation	9,749			



Part III Status of Reclamation and Mine Waste

Mine ID: 91

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: No

NAMLRP Project Number: NA-0101

NAMLRP Mine features: 2 Portals

The following information was obtained from field observations collected during the 2011 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed reclamation work and status:

Adits:

4 adits: Adit 1 - brick sealed, N side of canyon wall; Adit 2 - brick sealed, S side of canyon wall; Adit 3 - open, upon cliff on N wall; Adit 4 - possible adit above sealed adit on N canyon wall (Adit 1)

Waste Piles:

Waste rock piles below adits

Pits:

None observed

Shafts:

None observed

Other Debris and Mine Features:

Steel cables and wood mining debris; reclamation cap visible below Adit 1

Part IV Site Observations and Environs

Observed Residential Structures (number and human habitation status of structures at the following distances from the mine site):

0 to 200 feet: None observed

200 feet to 0.25 mile: None observed

Observed Public or Commercial Structures (schools, clinics, Chapter Houses, places of business and any other structures used by members of the community at the following distances from the mine site):

0 to 200 feet: None observed

200 feet to 0.25 mile: None observed

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed Water Sources (number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine site):

0 to 0.25 miles: None observed

0.25 miles to 4 miles: Colorado River approximately 1.75 mi W of site

Sensitive Environments (all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation):

None observed

Known Site History (information from interviews with Chapter officials and residents and database review, includes: mine ownership, type of mining operation, period of operation, known amount of production, and any other information provided):

The Jimmie Boone mine claim consists of an area of 75,546.36 m². The mine was identified as being operational in 1954. While operational, the mine had a total reported production volume of 14 tons. The mine surface land status is classified as Tribal Trust Land. Historical documents identified the operator of the mine as D.L., T.L., & F.E. Lee in 1954. No additional historical ownership / lease information was identified in the EPA / AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity? Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? Yes

Structures:

Were any structures observed within 200 feet of the mine? No

Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine? Yes

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Yes

Part VI Photos



Photo 1: Mine Site #91



Photo 2: Mine Site #91





Photo 4: Mine Site #91



Photo 5: Mine Site #91



Photo 6: Mine Site #91; Adit on north wall




Photo 7: Mine Site #91; Adits and reclamation area

Part VII Contacts Reports and Information

Name:	Eugene Esplain		
Title or official role (if any):	Navajo EPA Superfund Program		
Telephone number:	(928) 871-7331		
Address:	PO Box 2946, Window Rock, AZ 86515		
Information provided:	Lead Regulatory Agency		
N.			
Name:			
Title or official role (if any):			
Telephone number:			
Address:			
Information provided:			
Name:			
Title or official role (if any):			
Telephone number:			
Address:			
Information provided:			

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Jimmie Boone (91)
Bodaway / Gap Chapter, Navajo Nation





Figure 2 - Gamma Radiation Measurements Jimmie Boone (91) Bodaway / Gap Chapter, Navajo Nation



- 0 10,000 cpm
- 10,000 25,000 cpm
- 25,000 50,000 cpm
- 50,000 100,000 cpm
- 100,000 250,000 cpm
- 250,000 500,000 cpm
- 500,000 1,000,000 cpm

Measured as counts per minute (cpm)
Average background 12,338 cpm



General Slope Direction





